Tel: +86 15298811938 - Fax: +86 512 56738573

TO CUS	STOMER:			
序号	NAME	SIZE	NUMBER	READY OR NOT
	名称	规格	数量	是否准备好
1	ANGLE GRINDER		1 set	
	角磨机			
2	ELECTRIC HAND DRILL		1 set	
	手电钻			
3	ARGON ARC MACHINE		1 set	
	氩弧机			
4	ARGON		1 bottle	
	氩气			
5	CUTTING DISK	MODEL:	50 pcs	
	切割片	100		
6	LOUVER BLADE		50 pcs	
	百叶片			
7	NYLON WHEEL POLISHING WHEEL		30 pcs	
	尼轮抛光轮			
8	TWIST DRILL	10mm	2 pcs	
	麻花钻			
	TWIST DRILL	8mm	2 pcs	
	麻花钻			
9	304 STAINLESS STEEL WELDING WIRE	MODEL:	1 kilo	
	304 的不锈钢焊丝	1.6		
10	PET PREFORM		100,000PCS	
	瓶胚			
11	PET CAPS		100,000PCS	
	瓶盖			
12	LABELS		100,000 PCS	
	标签			
13	PE FILM		500KGS	
	聚乙烯薄膜			
14	CANS/LID		EACH	
	罐/盖子		100,000 PCS	
15	RAW MATERIAL TO MAKE		EACH	
	COLA/JUICE/OR RELATIVE PROUCTS		1000KGS	
	生产可乐/果汁/或相关产品的原料			
16	CARTON BOARD MATERIAL		10000 PCS	
	纸箱板材料			

Tel: +86 15298811938 - Fax: +86 512 56738573

No8 Xiangqun LeyuTown Zhangjiagang City Jiangsu Province China ,215600

Attachment:

序号	NAME	Picture
	名称	图片
1	ANGLE GRINDER 角磨机	
2	手电钻	END STATE AND
3	ARGON ARC MACHINE 氩弧机	OH POWER OF THE PO

Tel: +86 15298811938 - Fax: +86 512 56738573

4	ARGON 氩气	
5	CUTTING DISK 切割片	THE PARTY OF THE P
6	LOUVER BLADE 百叶片	

Tel: +86 15298811938 - Fax: +86 512 56738573

7	NYLON WHEEL POLISHING WHEEL 尼轮抛光轮	
8	TWIST DRILL 麻花钻	maan tuusti
	TWIST DRILL 麻花钻	
9	304 STAINLESS STEEL WELDING WIRE 304 的不锈钢焊丝	

Tel: +86 15298811938 - Fax: +86 512 56738573

10	PET PREFORM 瓶胚	
11	PET CAPS 瓶盖	
12	LABELS 标签	PAR 0.5 LITRE: Sucress Nutritionnels Journaliers. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. PAR 0.5 LITRE: Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. PAR 0.5 LITRE: Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit propre, frais et sec, à l'abri de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit de la lumiter. Buckes Livices Sconum Valeur Rustrit. Aconserver dans un endroit de la lumiter. Buckes Livices Rustrit. Aconserver dans un endroit de la lumiter. Aconserver dans un endroit de la lumiter. Aconserver dans un endroit de la lumiter. Aconserver dans un endroit de la lumiter de la lumiter de la lumit

Tel: +86 15298811938 - Fax: +86 512 56738573



Tel: +86 15298811938 - Fax: +86 512 56738573

No8 Xiangqun LeyuTown Zhangjiagang City Jiangsu Province China ,215600

15 RAW MATERIAL TO
MAKE COLA/JUICE/OR
RELATIVE PROUCTS
生产可乐/果汁/或相关
产品的原料



16 CARTON BOARD MATERIAL 纸箱板材料



Tel: +86 15298811938 - Fax: +86 512 56738573

No8 Xiangqun LeyuTown Zhangjiagang City Jiangsu Province China ,215600

INSTALLATION MACHINERY LINE MUST NEED FOLLOW ITEAMS:

序	NAME	READY OR
号	名称	NOT
		是否准备
		好
1	Sewage pipe should be connected well in advance.排污管道要提前连接好。	
2	The power supply and electric box should be prepared in advance. A single machine is	
	used as a single electric box (it is not safe to line everywhere in the workshop), especially	
	the bottle blowing machine, which has a large power, needs a separate electric box for	
	power supply,ensure voltage stability,if oltage instability requires a voltage regulator.	
	电源和电箱提前准备好,单台机器做单个电箱(车间内到处排线不安全),特别是	
	吹瓶机,功率很大,需要单独的电箱供电,确保电压稳定,电压不稳定需要加稳压器。	
3	The air source should be connected and installed in advance (prepare the air compressor	
	required by the filling machine and film packing machine in advance).	
4	气源要提前连接安装好(提前准备好灌装机、膜包机所需的空压机)。	
4	The water source should be prepared in advance, and the pipe connecting tap water or well water to water treatment should be connected in advance.	
	水源要提前准备好,提前连接好自来水或者井水到水处理的管道。	
_		
5	Prepare the juice granules in advance. The jar for storing the granules must be large enough to ensure the filling speed of the machine (the container size is 500 liters).	
	提前准备好果汁颗粒,存储颗粒的罐子必须要足够大才能保证机器的灌装速度(储	
	罐的容积大小500升)。	
6	Two hydraulic trucks should be prepared for use when moving the machine, and you can also use them when transporting products later.	
	液压车要准备好两辆,挪动机器的时候用,后期你运输产品的时候也可以用。	
7	Piping from water treatment to mixing system should be prepared and connected in	
,	advance.	
	水处理到混合系统的管道要提前准备并连接好。	
8	The bottle embryo required by the bottle blowing machine is prepared in advance (the	
	correct size has been provided in the group, and the correct bottle embryo is also in the	
	machine).	
	吹瓶机需要的瓶胚提前准备好(正确的尺寸,机器里面也有正确的瓶胚)。10000pcs	
9	Prepare juice ingredients in advance.调配果汁的原材提前准备好。	
10	10. The correct label of the label machine should be prepared in advance.	
	套标机的正确标签要提前准备好。	
11	Prepare the membrane required for the film packing machine in advance.	
	膜包机所需要的正确卷膜需要提前准备好。	
12	Prepare two phone cards in advance for engineers to communicate with .	
	提前准备两张电话卡给工程师沟通联系用。	
13	Arrange accommodations for engineers in advance.	
	提前安排好工程师的住宿问题。	

Tel: +86 15298811938 - Fax: +86 512 56738573

No8 Xiangqun LeyuTown Zhangjiagang City Jiangsu Province China ,215600

14	All the tools are ready in advance.工具都提前准备好。	
15	The 7-ton forklift should be ready in advance.7 吨的叉车要提前准备好	
16	Customers in the local must have an experienced beverage mechanical engineer who	
	understands the machine principle and electrical principle.	
	客户当地一定要有一名有经验的饮料机械工程师懂的机器原理和电气原理。	
17	There must be 3-4 local staff to cooperate with our engineers and learn the machine	
	operation process at the same time	
	配备 3-4 名工作人员配合我们工程师连线,同时学习机器操作流程	
18	If the above list is not ready due to the customer's reasons, the factory will not bear the	
	responsibility for the delay, and the debugging cost caused by the delay will be borne by	
	the customer.	
	如因客户原因以上清单没有准备好,导致的延误工厂不承担责任,届时延时产生的	
	调试费一律由客户承担。	
19	The ticket must be a round-trip,unchangeable order.机票必须是来回不可改的定单。	
20	If filling a beverage containing gas, it is necessary to prepare carbon dioxide and the	
	correct ventilation pipe in advance	
	如果灌装含气的饮料,需要提前准备好二氧化碳以及正确的通气管道	
21	If did not buy the raw water pump, need to prepare the required raw water pump in	
	advance	
	如果没有买原水泵,需要提前准备好所需的原水泵	
22	If the filling line have water treatment, also have not purchased the raw water tank in our	
	company, need to prepare the raw water tank in advance	
	有水处理的话,如果没有在我公司购买原水罐需提前准备好原水罐	
23	Check in advance whether there is a domestic power supply in the factory and how much	
	voltage it is	
	提前确认好工厂里面是否有家用电源,是多少电压	
24	Confirm the power of the machine in advance, and arrange enough power supply wires to	
	ensure that all the machines can withstand when they are turned on at the same time	
	提前确认好机器功率,配足足够大的进电电线,确保所有的机器在同时开启的时候	
	能承受得住	
25	Check whether the plant voltage is warm in advance, and prepare the regulator in	
	advance if it is unstable	
	提前检查工厂电压是否温度,如果不稳定的话提前准备好稳压器	
26	The raw materials required in the use of the machine, such as the chiller needs to prepare	
	antifreeze, and the generator needs to prepare diesel and antifreeze in advance	
	机器使用过程中需要的原料,如冷水机需要准备防冻液,发电机需要提前准备柴油	
	和防冻液	

Customer sign and seal:

Date: